户泊洋國際企業有限公司 POMAG INTERNATIONAL CO., LTD. 8F-2, 126 CHUNG-TE RD. SEC.2. TAICHUNG, TAIWAN TEL 886-4-22304321, 22304322 FAX 886-4-22304777

Example Report

PHYSICAL INSPECTION REPORT					🗌 Durin	g		Final 🗌 Re-ir	nspectio	on
P.O. Number	980915DEL1-1 Description			ALL	BAME	BOO LAN		ON RAC	KET	
Item Number	72679 Merchandiser			Lyc	lia Jan	1	Inspection Date	200	09/11/30	
Client	M-001							ETD Date	200)9/12/07
Factory	CH-001						Country of Origin	T/	AIWAN	
Shipment	🗹 SEA	AIR		OTHER	FCL	\checkmark	LCL	Goods Export To	GE	RMANY
Order Q'TY	1,200	PCS IN	24	CTNS	Shipped C	Q'TY	1,20	0 PCS IN	24	CTNS

Packaging Information		Carton Dimension	Measurement	N.W. / G.W.	Compliance With Request?
Master Carton	50 PCS	67.0 x 39.0 x 31.0 cm	2.86'	7.00 / 7.90 KGS	YES
Inner Carton	N/A	N/A	N/A	N/A	N/A

Packaging Identification	Pass	Fail	N/A	Product Identification	Pass	Fail	N/A
Master Carton Shipping Mark?	\checkmark			Check With Approval SMPL?	\checkmark		
Master Carton Side Mark?	\checkmark			Check Product Spec. & Size?	\checkmark		
1C-3E-6S Drop Test (=25kg 24" H)</td <td>\checkmark</td> <td></td> <td></td> <td>Check Product Safety Test?</td> <td>\checkmark</td> <td></td> <td></td>	\checkmark			Check Product Safety Test?	\checkmark		
Inner Carton Shipping Mark?			\checkmark	Product Appearance?	\checkmark		
Inner Carton Side Mark?			\checkmark	Product Construction?			\checkmark
Color Box or Color Card?			\checkmark	Product Function?	\checkmark		
UPC Code?			\checkmark	Material Used?	\checkmark		
Any Labeling / Sticker Request?			\checkmark	Product Color?	\checkmark		
Polybag With Warning?	\checkmark			Check The Instruction Sheet?			
CE/ GS/ TUV/ UL/ ETL Marking?			\checkmark	Assembly Test?			ND
Warning & Instructions?			\checkmark	Testing Certificate?			
Country of Origin?	\checkmark			Factory Certificate?		$ \mathbf{d}\rangle$	
SMPL Taken? I YES NO	Q'ty:	1	PCE	The Percentage of Mass Production	on: 10	0%	
Remark:				Remark:	IM		
			\\ (L	Badminton Racket Size 660 mm	x 200 mm	x 10 mm	

Quality Inspection - Single S	Sampling Plan MIL-STD 105E	Normal: AQL	.Level I 🗹 AG	QL. Level II
Lot or Batch Size	1,200 PCS	Critical (0)	Major (2.5)	Minor (4.0)
Plan Sample Size	80 PCS	0	5	6
Actually Sampling Size	100 PCS / 2 CTNS	0	0	4

DEFECTS CLASSIFICATION						
DETAIL OF DEFECTS	Critical	Major	Minor			
Small Pit on Badminton Racket	0	0	2			
Color Discrepancy on Joint Position	0	0	2			
TOTAL	0	0	4			

Special Comments / Remark:

INSPECTION RESULTS:

Correction Required

Rejected Pending

1/30.09 T

Fich Due

2/3 Malya

2009/11/30

 \square

Accepted

Factory's Signature & Date

Inspector's Signature & Date

Sales Executive

This certification/report does not discharge or release sellers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. All the defective pieces found at the inspection should be discarded and replaced.

户户注國際企業有限公司 FF-2, 126 CHUNG-TE RD. SEC.2. TAICHUNG, TAIWAN TEL 886-4-22304321, 22304322 FAX 886-4-22304777







户户泊洋國際企業有限公司 POMANG INTERNATIONAL CO., LTD. 8F-2, 126 CHUNG-TE RD. SEC.2. TAICHUNG, TAIWAN TEL 886-4-22304321, 22304322 FAX 886-4-22304777





